



2.2 kW Inverter Parameter Setting

INVT 2.2KW

CHP110A

P.0.01=1 Speed Control

P0.07 =1 Frequency Selection

P6.02=4 Relax output selection

P0.11=5 Acceleration Time

P0.12=5 Deceleration Time

P0.13=2 Running Direction

P4.01=7 Motor Torque Boost

P5.01=1 Forward Terminal Selection

P6.04=3 Output Selection

P7.00=11111 Password



www.lfamachines.com

| | |
|--------------|--------------|
| Drawing Name | RTP 10i |
| Product Name | RTP 10i |
| Version | 1.0 |
| Provided By | LFA Machines |