



SW1	SW2	SW3	
ON	OFF	ON	0-10V
ON	ON	OFF	0-20mA



www.lfamachines.com

Drawing Name	RTP 10i wiring diagram
Product Name	RTP 10i
Version	1.0
Provided By	LFA Machines