



Key

- K = Switch
- R = Potentiometer
- V = Rectifier Tube
- B = Electromagnet
- X = Linker

Note: The interval between the upper side of the electromagnet and the bottom of the armature should be 1.5 mm to 2.5 mm.



www.ifamachines.com

Drawing Name	UHDD Electrical Drawing
Product Name	UHDD
Version	V 1.0
Provided By	Callie Scott